Appln No. 10/760275 Amdt. Dated: December 21, 2006

Response to Office Action of October 19, 2006

2

Amendment to the Specification

The second paragraph beginning at Page 2, line 7 through to page 3 line 4, is to be amended as follows:

CROSS-REFERENCE TO CO-PENDING APPLICATIONS

The following applications have been filed by the Applicant simultaneously with the present application:

10/760230	10/760225	10/760224
10/760242	10/760228	10/760250
10/760215	10/760256	10/760257
10/760240	10/760251	10/760266
10/760239	10/760193	10/760214
10/760260	10/760226	10/760269
10/760199	10/760241	10/760272
10/760273	10/760187	10/760182
10/760188	10/760218	10/760217
10/760216	10/760233	10/760246
10/760212	10/760243	10/760201
10/760185	10/760253	10/760255
10/760209	10/760208	10/760194
10/760238	10/760234	10/760235
10/760183	10/760189	10/760262
10/760232	10/760231	10/760200
10/760190	10/760191	10/760227
10/760207	10/760181	10/760254
10/760210	10/760202	10/760197
10/760198	10/760249	10/760263
10/760247	10/760223	-10/760264
10/760244	10/760245	10/760222
10/760248	10/760236	10/760192
10/760203	10/760204	10/760205
10/760206	10/760267	10/760270
10/760259	10/760271	10/760275

Appln No. 10/760275 Amdt. Dated: December 21, 2006 Response to Office Action of October 19, 2006

3

10/760274	10/760268	10/760184
10/760195	10/760186	10/760261
10/760258	10/760180	10/760229
10/760213	10/760219	10/760237
10/760221	10/760220	10/760211
10/760252	10/760265	

10/760272	10/760273	7083271	10/760182	7080894
10/760218	7090336	10/760216	10/760233	10/760246
7083257	10/760243	10/760201	10/760185	10/760253
10/760255	10/760209	10/760208	10/760194	10/760238
<u>7077505</u>	10/760235	<u>7077504</u>	10/760189	10/760262
10/760232	10/760231	10/760200	10/760190	10/760191
10/760227	10/760207	10/760181	10/760254	10/760210
10/760202	10/760197	10/760198	10/760249	10/760263
10/760247	10/760223	10/760264	10/760244	10/760245
10/760222	10/760248	7083273	10/760192	10/760203
10/760204	10/760205	10/760206	10/760267	10/760270
10/760259	10/760271	10/760275	10/760274	10/760268
10/760184	10/760195	10/760186	10/760261	7083272
10/760180	10/760229	10/760213	10/760219	10/760237
10/760221	10/760220	7002664	10/760252	10/760265
10/760230	10/760225	10/760224	<u>6991098</u>	10/760228
<u>6944970</u>	10/760215	10/760256	10/760257	10/760240
10/760251	10/760266	6920704	10/760193	10/760214
10/760260	10/760226	10/760269	10/760199	10/760241

Appln No. 10/760275 Amdt. Dated: December 21, 2006 Response to Office Action of October 19, 2006

4

The paragraph beginning at Page 25, lines 3 - 6, is to be amended as follows:

Referring now to Figure 40, the first step of the ink refilling procedure is initiated by refill sensor 35 indicating to controller board 82 that there is a deficiency of printing fluid in storage reservoirs 28, 30, 32, 34. In response to the signal from the refill sensorink-cartridge QA-chip that the ink is nearly depleted, controller board 82 activates indicator LED 138-to inform the user that another refill is necessary.